


**FIG. 1**

(a)



(b)






FIG. 2

8A } INSPECTION LIGHT BEAM  
8B }



7 CHIPPING DEFECT 4 PHASE-180° SHIFTER PORTION 5 PHASE-0° PORTION 6 PROTRUSION DEFECT

FIG. 3



**FIG. 4**




FIG. 5




FIG. 6

